

- Found Monument (see field notes) O - Set Monument (see field notes)

M - Measured this survey

P - Plat Distance

Points #7, #9 & #14 - Found $\frac{1}{2}$ " Rebar with stamped plastic cap as recorded by Eugene R. Schiltz, LS #288.

Points #8 & #10 - Found ½" Rebar with stamped plastic cap as recorded by Eugene R. Schiltz, LS #288. Did not use.

Point #11 - Found ½" Rebar as recorded by Eugene R. Schiltz, LS #288.

Points #12 & #15 - Set %" X 30" Rebar with stamped plastic cap.

SURVEYOR'S CERTIFICATE


I, Steven L. Rasmussen, a registered surveyor of the State of Nebraska, hereby certify that this survey was made by me or under my direct supervision on June 22nd, 2011; that all dimensions are in feet and are correct to the best of my knowledge and belief.



Steven L. Rasmussen, Nebraska L.S. #524 Rasmussen Land Surveying, LLC

THE WEST 1/2 OF LOT 3, ALL OF LOT 4 AND THE EAST 1/2 OF LOT 5, BLOCK 7, KIKER'S ADDITION TO THE VILLAGE OF SARGENT, CUSTER COUNTY, NEBRASKA.

LEGAL SURVEY



Date Drawn By 06/24/11 DEH Project #HR1595 1"= 50' Field Book 13 File Name SOK.DWG Revision Revision Sheet 1 of 1

This plat was prepared at the request of Gene Sok, Sargent, Nebraska.

Rasmussen Land Surveying, LLC 85774 US Highway 281 O'Neill, Nebraska 68763 Phone/Fax: (402) 482–5851

1" = 50'